

Sul Ross Industrial Technology IT 2316 Iron Working I

Fall 2022

Instructor

Jim Low, Adjunct Professor

Office: 101, Industrial Technology Building

Phone: 432-837-8210 Email: jfl19gb@sulross.edu Office Hours: By appointment

Time and Location

MW 3:00 pm - 5:00pm - Lab Room 108, Industrial Tech Building

Course Description

Basic skill development in hand-forging skill, forge welding, scroll-forming, shaping joinery utilizing hammers, anvils and coal and gas forges. Emphasis on techniques and processes to demonstrate versatility and skill.

Course Objectives

- To become familiar with forging hot iron using basic blacksmithing techniques with forge, hammer and anvil.
- 2. To demonstrate safety throughout all procedures in metal-working lab and the development of thoughtful work habits.
- 3. To identify and discuss design benefits of traditional blacksmithing techniques.

End of Course Outcomes

Students will demonstrate facility with forging hot iron, acquire appropriate metal-working safety procedures and understand traditional blacksmithing design techniques.

SRSU Disability Services

Sul Ross State University (SRSU) is committed to equal access in compliance with Americans with Disabilities Act of 1973. It is SRSU policy to provide reasonable accommodations to students with documented disabilities. It is the student's responsibility to initiate a request each semester for each class. Students seeking accessibility/accommodations services must contact Rebecca Greathouse Wren, LPC-S, SRSU's Accessibility Services Coordinator at 432-837-8203 (please leave a message and we'll get back to you as soon as we can during working hours), or email rebecca.wren@sulross.edu. Our office is located on the first floor of Ferguson Hall (Suite 112), and our mailing address is P.O. Box C-122, Sul Ross State University, Alpine. Texas 79832.

Library Information

The Bryan Wildenthal Memorial Library in Alpine offers FREE resources and services to the entire SRSU community. Access and borrow books, articles, and more by visiting the library's website, <u>library.sulross.edu</u>. Off-campus access requires logging in with your LoboID and password. Librarians are a tremendous resource for your coursework and can be reached in person, by email (<u>srsulibrary@sulross.edu</u>), or phone (432-837-8123).

The Southwest Texas Junior College (SWTJC) Libraries at Uvalde, Del Rio, and Eagle Pass. Offer additional access to library spaces and resources. Del Rio, Eagle Pass, and Uvalde students may also use online resources available through SWTJC website, library.swtjc.edu. The SWTJC Libraries serve as pick-up locations for Inter-Library Loan (ILL) and Document Delivery from the Alpine campus.

Diversity Statement

"I aim to create a learning environment for my students that supports a diversity of thoughts, perspectives and experiences, and honors your identities (including race, gender, class, sexuality, religion, ability, socioeconomic class, age, nationality, etc.). I also understand that the crisis of COVID, economic disparity, and health concerns, or even unexpected life events could impact the conditions necessary for you to succeed. My commitment is to be there for you and help you meet the learning objectives of this course. I do this to demonstrate my commitment to you and to the mission of Sul Ross State University to create an inclusive environment and care for the whole student as part of the Sul Ross Familia. If you feel like your performance in the class is being impacted by your experiences outside of class, please don't hesitate to come and talk with me. I want to be a resource for you."

Classroom Climate of Respect

Importantly, this class will foster free expression, critical investigation, and the open discussion of ideas. This means that all of us must help create and sustain an atmosphere of tolerance, civility, and respect for the viewpoints of others. Similarly, we must all learn how to probe, oppose and disagree without resorting to tactics of intimidation, harassment, or personal attack. No one is entitled to harass, belittle, or discriminate against another on the basis of race, religion, ethnicity, age, gender, national origin, or sexual preference. Still, we will not be silenced by the difficulty of fruitfully discussing politically sensitive issues.

Incomplete Grades

Strive to complete work on time. A grade of incomplete is given only if you can substantiate why work was not completed due to insurmountable schedule conflicts that occurred after final date of withdrawing from course. The incomplete grade must be removed the deadline during the following semester or <u>it will convert to a final grade of "F".</u> Consult calendar in current college catalogue for removal date during the following semester period. <u>It is not your instructor's responsibility to remind you of this date.</u>

Grading Policy

Your final grade will be based on progress throughout semester in the areas of applied skills (projects) and theory (examinations), waited as follows:

Projects 60%
 Examinations 40%

Your applied skills will develop as you progress through the Project List in this syllabus. The project list contains important accumulative projects, so your final applied skills grade will be based on the percentage of projects you complete.

Design theory is also an important part of this course. While applied skills are invaluable for learning what to do, a metalsmith must know the theory behinds what happens. Your instructor will provide appropriate written exams to measure your understanding of metalsmithing theory.

When calculating the above percentages, the following grading system is used at Sul Ross University:

A – Excellent	90% - 100%	grade point 4
B – Good	80% to 89%	grade point 3
C – Average	70% - 70%	grade point 2
D - Minimum Pass	60% to 69%	grade point 1
F – Fail	59% to 00%	grade point 0

Safety Regulations

Metal work is inherently dangerous and can become very dangerous, even fatal, if you are careless and neglect safety precautions. Most accidents occur when people get in a hurry, so learn to pace yourself and move cautiously and deliberately. The university endeavors to provide you with proper training and a safe environment, but you must also do your part by abiding by the following rules. *If you persistently violate these rules, you will be considered a safety risk and will be withdrawn from class:*

- Be aware of the following: Equipment on/off switches, gas valves, fire extinguishers, labexits, first aid kit. Campus police emergency number is 432-837-8011, 911 off campus. Follow all posted safety procedures.
- 2. Welding and metal work is inherently dangerous. Be alert; do not work if you are drowsy, intoxicated, hung-over or taking medication that affects judgment
- 3. Beware of the signs of dehydration, especially during warm months: disorientation, confusion, light-headedness, flushed appearance, headache, and exhaustion. Do not wait until these signs appear drink fluids and take frequent breaks.
- 4. Be mindful of proper ventilation in your work area.
- 5. Wear eye protection at all times. Wear hearing protection, especially when using or near power tools.
- 6. Dress properly when working with or welding hot metal. Shorts or sandals are not permitted. Wear long sleeves or leathers, work boots, and gloves while welding. (see Supply List)
- 7. Be sure that you have the proper shade of filter lens in your welding glasses, helmet or face shield.
- 8. Do not wear loose clothing or dangling jewelry in the lab. Tie up long hair.
- 9. If you burn yourself, cool the burn with cool water. Know where the first aid kit is and what its contents are. Alert your instructor to evaluate any injury!
- 10. Report all accidents to your instructor immediately. If you suspect an unsafe condition, bring it to your instructor's attention IMMEDIATELY!
- 11. Respect your fellow student; avoid all operations such as haphazardly grinding, heating or hammering that creates an injurious environment. Respect all of the equipment: it is durable but not indestructible: avoid damaging the school equipment.
- 12. Do not use any tool or equipment on which you have not been properly trained.
- 13. Never allow tools to become overheated. If tools accidentally are heated, allow them to cool in air; never quench them.
- 14. Notify your instructor if hammers or struck tools have mushroomed and cracked, or if the head is loose or handle is damaged.
- 15. Preserve cutting edges on hand tools and anvil tools.
- 16. Be extremely careful with the torch, it will burn the skin instantly.
- 17. Do not weld or grind near oxy-fuel tanks, manifold connections, or other potential sources forgas leaks.
- 18. Do not handle oxy-fuel equipment with oil or grease on your hands or clothing.

- 19. Never use acetylene gas at working pressures above 15 psi.
- 20. Never move or unchain a cylinder without first removing the regulator and putting the appropriate cap over the valve.
- 21. Always clamp pieces at the drill press, unless otherwise instructed.
- 22. When using portable grinders, be sure that you direct sparks away from others. Only grind in areas designated by your instructor, and always be sure to sweep up your grinder dust. It poses a serious slip hazard.
- 23. When using stationary pedestal grinders, be sure that the tool rest is adjusted as close to the grinding wheel as possible without touching it. Always wear safety glasses and a face shield when grinding and wire brushing. Do not wear gloves when working at pedestal/ bench grinders.
- 24. Never carry hot work, long pieces or sharp ends projecting in front of you, possibly injuring someone. Always carry work at your side. Avoid placement of your work that could present a puncture or trip hazard.
- 25. To avoid burns to others, do not discard hot metal without first quenching it. Write "HOT" on objects too large to bring to quench tank. In addition, if there is any work on the ground assume that it hot. Tap it to test before grasping.
- 26. Allow absolute unobstructed room around a striker swinging a sledgehammer; never walk behind a person striking with a sledgehammer.
- 27. Do not remove someone else's tools from his or her workstation.
- 28. Do not quench any steels unless you know what you are working with or intentionally need to heat/treat.
- 29. Not all steel is the same unless it comes off the rack and do not assume it is weldable, forgeable or can be sheered in hydraulic sheers or saws.
- 30. Do not attach your ground lead to water pipes or electrical conduit.
- 31. When welding in open lab, shield your arc with welding curtains. Always consider the line of sight between your arc and the eyes of bystanders.

Laboratory Policy

- 1. You must attend class at the time for which you are enrolled
- 2. When you complete a project, request approval from your professor. You will not be credited for unapproved projects.
- 3. Cleanup time is ten minutes before the end of class. Sweep your immediate work area and return equipment to tool room. Surrounding work areas must be cleaned with collaborative effort of all students
- 4. Do not waste metal. Do not remove metal from the shop.
- 5. If there is an equipment malfunction, inform instructor immediately for repair and return to service.
- 6. Smoking/vaping is not permitted.

Course Outline 16 Week Semester

Week 1 Introduction, syllabus, schedule, safety policies, lab familiarity, torch introduction, blacksmithing vocabulary, introduction to ergonomic system of forging

Week 2	Safety exam, design, present day relevance of craft, ergonomic, hammer control drawing steel, cutting with hardy, flat tapers, pointed tapers, round tapers
Week 3	Estimation of stock, bending, shouldering, spreading, fullering, punching, veining
Week 4	Forging to dimension, forging to finish, pre-figuring
Week 5	Upsetting, fly press work, grooving
Week 6	Grinding, sharpening, splitting, slitting and drifting
Week 7	Fire welding
Week 8	Fixtures, forms and jigs
Week 9	Line and shape adjustments
Week 10	Drills and drilling
Week 11	Hacksaws, files, hot rasping
Week 12	Fitting
Week 13	Tenons and wraps
Week 14	Riveting
Week 15	Swaging and collaring
Week 16	Finishes

Safety Agreement Sul Ross University Industrial Technology

By signing my name below, I am attesting that my instructor has made me aware that <u>welding is dangerous</u> if I ignore applicable safety regulations and laboratory policies. I understand that I will acquire the knowledge of these regulations and policies by (1) reading the course syllabus attached to this Safety Agreement, (2) reading the chapters on safety in my textbook (if applicable), (3) observing all safety and warning signs posted in the laboratories and classroom, and (4) attending in-class safety demonstrations on equipment and shop practices given by my instructor throughout the course. I understand that it is my responsibility to attend class regularly, be alert to my surroundings and remain constantly vigilant to the risks of working in an industrial environment. I understand that "safe practice" is the discretionary interpretation of my instructor, and that if I fail to adhere to these requirements – *including the attendance policy outlined in the syllabus, I will be considered a safety risk to myself and others and I may be withdrawn or possibly fail the course.*

Student (print name)	Student signature
Student phone	Student Email
Instructor	Year
Emergency Contract Person	Emergency Phone

